

DART system Report

System in the West has had couple problems since last meeting. Power switch not turned on power strip(very minor) and next weekend the guns were not being sensed, then not shooting at top of screen. Second Chapter's problem, they tried repairing on their own before calling. I had them stop what they were doing and reboot, then the guns were being sensed. They called an hour later with the shots being missed at top of screen and I talked them thru realigning the camera to the projector (which was fine the weekend before).

System has one more event this year, end of October, then I intend to work on it to secure the Projector and the other components better.

System in the East has completed all scheduled events for the year. Sun Area Chapter has it and they are the first event of the 2009 schedule.

When I got it at the last meeting, it wasn't sensing the guns at all. After several days of working on it with and without the Dart system guys help, I realized that the power transformer the had previously been replaced by one chapter ,that felt the original had melted, was too high a voltage and I reused a transformer from the original Dart system and it's working fine again.