

## Dart Committee Report

### Short Version:

WEST system had problem booting, worked on it and had that resolved. Realigned shot sensor to projector, suspect someone raised projector angle. Power transformer was reported as melted and replaced by chapter. Then it quit booting again. Remote also missing, replaced with new. Tested for a week for reboot problem. Sent it out and it was reported as not sensing gun shooting. Trying to get it returned to work on it.

EAST system was sent from one event to another with a gun sensing problem and Screen crankscrews missing. When I got it back, Projector was falling out of back of case when back was removed. Replaced Velcro for Remote, black box and checked cabling, changed strap on Projector to be front to rear. At two events later, it only displays a green screen when in Turkey shooting, clay bird, etc okay. Got unit returned and found projector strap was loosened and slipped off unit. Discussed problem with DART and they feel the video card needs recalibrated. Is to be sending me the program via email. Hope to get it working for this weekend's event in the west.

Update at Board meeting.

Tom Bunty