

Dart System Report March 2010

When checking out the East system before it went out for the first Event, I found that one of the 410's would only fire once in ten – twenty minutes and new batteries didn't fix the problem. Ordered and Installed new Laser @ \$500 plus shipping \$30. Laser that failed had date of 09/99, must be original. Didn't get it repaired before the ESOS. I have it at home yet. Will test when I have the system in April.

At first Event, Bloomsburg Early Bird show, they called on Friday and couldn't get it to sense any shots, though it had worked for prior day and half. Tried talking them thru troubleshooting but couldn't get it working.

Went up to Show early Sat. morn and found that the right side mount of the camera hinge bolt had come out and Coax cable on rear of Camera was off back of camera and hanging mid air. Reinstalled coax and system working again, reinstalled mount bolt and tightened.

West system started it's tour without any problems.

Tom Bunty